



## Steering Wheel Radio Controls

### Interfacing Information Bulletin Number 4

8-10-01

#### Aftermarket

**Stereos:** Pioneer AVXP7000CD, AVXP7000, AVMP7000R, AVMP8000R, AVMP9000R, GEXP7000TV, Sony products that uses the wireless rotary commander, RM-X112, RM-X110, RM-X114 remotes, and Rockford Fosgate

**Symptom:** After programming the SWI interface, the steering wheel buttons will not work the aftermarket stereo.

**Reason:** The infrared remotes have a longer data signal that the SWI interface cannot capture completely. As a result the SWI only sends out partial data signal, which the Pioneer head unit does not recognize.

**Solution:** We are currently working on a fix. When have a fix, we will post an update on our website.