



OEM-1

Interfacing Information Bulletin **Number 4**

April 22, 1998

Vehicles: Early model 1984 General Motors vehicles with Delco/ Bose, mostly Corvette.

There are only a small quantity of these vehicles. Not all 1984's

Product: AMP-GM12, OEM-1, any aftermarket head unit cable

Symptom: The right front and right rear speakers may not work or be at a reduced volume.

Correction: 1) Cut the gray/ black and purple/ black wires close to where they currently connect to the black wire. Insulate the exposed ends left on the black wire.

2) Cut the short white/ black and short green/ black wires that loop into two pins of the Molex connector. Cut these wires close to the splice with the white/ black and green/ black wires that go to the vehicle connector. Insulate the exposed ends left on the long wires.

3) Connect the long gray/ black wire cut in step 1 to the short white/ black wire cut in step 2. Connect the long purple/ black wire cut in step 1 to the short green/ black wire cut in step 2. Insulate all splices carefully.