



## OEM-1

### Interfacing Information Bulletin **Number 1**

March 31,1998

**Vehicles:** 1992 Chevrolet Lumina. Vehicles with one Delco/ Bose amplifier located in the trunk.

**Product:** AMP-GM21, OEM-1, any aftermarket head unit cable.

**Symptom:** When replacing the factory head unit the rear speakers may not work or be at very low volume. Front speakers work fine.

**Correction:** On the AMP-GM21 harness, connect the green/black wire and gray/black wires together.

**Cause:** Some vehicles that have only one amplifier for the four speakers use one common audio return wire, instead of two. ( one for front and one rear) The AMP-GM21 harness is made for the more popular systems that use two audio return wires. Connecting the green/black and the gray/black commons all four audio channels.